

INSTALLATION INSTRUCTIONS

Replacement Flat Gasket for A0030-124S Swivel Fill Adapter and A0076-124S Swivel Vapor Adapter.

Service Tools Required:

- Ratchet Wrench
- 15/16" Socket
- 5/32 " Allen Wrench
- Torque Wrench w/ 60 to 75 ft-lbs Setting
- EMCO Adapter Wrench p/n A0081-001

CAUTION:

Always barricade to keep pedestrians and vehicles from accessing the storage tank area during preventive maintenance and/ or compliance testing of the EMCO phase I EVR system.

1. Begin by removing the lid from the A1004EVR spill containment and fill or vapor adapter cap. Using a 5/32" allen wrench, remove both set screws from the base of the A0030-124S swivel fill adapter or A0076-124S swivel vapor adapter.
2. Use the EMCO Adapter Wrench p/n A0081-001 to unscrew the A0030-124S swivel fill adapter or A0076-124S swivel vapor adapter from the top of the containment nipple.



Flat
Gasket



3. Remove the existing flat gasket and replace with new.

4. Before installing the A0030-124S swivel fill adapter or A0076-124S swivel vapor adapter, verify that the flat gasket is secured in place. Manually tighten the A0030-124S swivel fill adapter or A0076-124S swivel vapor adapter onto the containment nipple to avoid cross threading. Using the EMCO Adapter Wrench p/n A0081-001, tighten and torque between 60 to 75 ft-lbs.

IMPORTANT: Do not use pipe thread sealant compound when installing the A0030-124S swivel fill adapter or A0076-124S swivel vapor adapter onto the containment nipple.

5. Re-install both set screws to the base of the A0030-124S swivel fill adapter or A0076-124S swivel vapor adapter and tighten.

IMPORTANT: Leave these installation instructions, product warranty registration card and the warranty tag with the station owner and/or operator.

Emco Wheaton Retail Corp.

2300 Industrial Park Dr. • Wilson, NC 27893
252-243-0150 • 252-243-4759 (fax)

p/n 568602
Rev. D, 04/17